




Note - Supply voltage must be 10 volts higher than maximum controller voltage. On a 0 to 10 volt controller the minimum supply voltage required is 20 volts.



AirTest Technologies Inc

TR-5200 WIRING

Drawn By: dcm | Drawing No.: TR5200W/Wire.tdw | Rev: